Project Summary and Justification							
Department	Lincoln City Libraries						
Division							

### **Project 1** Bennett Martin Public Library Renovation

The Bennett Martin Public Library, constructed in three phases (1962, 1968, 1978) is in need of renovation. Renovation will provide an updated facility which would meet current ADA standards. The renovation will include a complete replacement of the heating, ventilating, and air conditioning systems as well as replacement of a significant portion of the furniture and fixtures. Based on information provided in the 2003 Bennett Martin Public Library Space Needs & Facility Study and the 3% per year inflation factor this equates to \$10,787,800 in 2008/2009 dollars. The Planning Department will be undertaking a Downtown Master Plan study in 2004. Results of this study may impact this project.

# **Project 2** Gere Branch Library Parking Lot Resurfacing

The Gere Branch Library parking lot and accompanying drives, approximately 46,000 square feet, were constructed in 1971. In 1986 they were overlaid utilizing 2" of Type III asphalt and petro-mat. In 1993 approximately 16,000 square feet of additional parking area was added as part of the Gere Branch expansion project. In the fall of 1996 potholes began appearing in the surface of the lot. The lot has been adequately maintained through repairs for a period of approximately 5 years. In addition to the resurfacing of the entire lot, structural repairs are required on a minimum of 10% of the lot surface area prior to resurfacing operations.

#### **Project 3** South Branch Library Roof Replacement

The current roof, a loosely laid, ballasted, EPDM membrane system, was installed in 1986 and was warranted for a period of ten years. During the summer of 1998 we began to experience problems with leakage. Multiple repairs were made extending the life of the roof by approximately 5 years. It is recommended that the roof be replaced in fiscal year 2003-2004; however, due to funding limitations request is being made for funding in FY 2005-2006.

#### Project 4 Bennett Martin Public Library Roof Replacement, South Portion Unit #1

This roof is a loosely laid, ballasted, EPDM membrane system. Installation was completed in the fall of 1987 and is covered by a 15 year water-tight warranty. This warranty expired in the fall of 2002. Based on current experiences it is requested that this roof be replaced in FY 2002-2003; however, due to funding limitations request is being made for funding in FY 2005-2006.

#### Project 5 Bethany Branch Library Roof Replacement

The existing roof is a fully adhered EPDM membrane system. It was installed in 1989 and carries a 15-year watertight warranty. Based on current experiences it is recommended that this roof be replaced when the warranty expires in 2004. However, due to funding limitations, the request for funding is being made in FY 2005-2006.

# **Project 6** Bennett Martin Public Library Cooling Tower Replacement


The cooling tower serving unit #3 (3<sup>rd</sup> & 4<sup>th</sup> floors) at Bennett Martin Public Library needs to be replaced due to deterioration of the tower body. The cooling tower was installed in 1978 as part of the Unit #3 addition. Problems with corrosion damage to the tower structure have plagued us since 1994. During this time period we have replaced the air plenum and a section of the tower wall. We have also sealed numerous small leaks


Department	Lincoln City Libraries
Division	
uilding, which is emoved and rep includes funds to e replaced in FY	section of the tower. Currently the cooling tower is located within the confines of the makes service difficult and necessitates that a portion of the north wall of the building belaced to allow for replacement of the cooling tower. The cost of replacing the tower move the cooling tower to the roof. We have determined that the cooling tower needs to 2002-2003 at a cost of \$54,300. However, due to general revenue limitations, the project in FY 2006-2007 at a cost of \$50,000, which includes no inflation factor.
The current roof, ear 'no leak' wane roof; in addit ummer/fall of 2 epair leaks. The roject will entail	Bennett Martin Public Library Roof Replacement, West Portion Unit #1 a loosely laid, ballasted, EPDM membrane roof was installed in 1991and carried a 10- arranty. In the spring of 2003 leaks were discovered along the East and North sides of ion, significant shrinkage was observed across the field of the roof. During the 003 extensive repairs were made to the roof to relieve tension caused by shrinkage and the se repairs are expected to extend the useful life of the roof by five (5) years. This I removal of the existing roof membrane and all related components. A new EPDM with a 15-year 'no leak' warranty and all related hardware will be installed.

This page left blank intentionally.

# *Lincoln CIP* 2004 - 2010

# Libraries





List of Projects Department: Lincoln City Libraries

Project Project Number Title

- 1 Bennett Martin Public Library Renovation
- 2 Gere Branch Parking Lot Resurfacing
- 3 South Branch Library Roof Replacement
- 4 Bennett Martin Public Library, South Portion, Unit 1, Roof Replacement
- 5 Bethany Branch Library Roof Replacement
- 6 Bennett Martin Public Library Cooling Tower Replacement
- 7 Bennett Martin Public Library Roof Replacement, West Portion Unit #1

<sup>\*</sup> Indicates project is **NOT** shown on the map.

			DEPARTMENT:	LIBRARY				FORM A		
2004 -	2010 CAPITAL IMPROVEMENT PROGRAM		DIVISION:	ADMINISTRATIO	N					
(1)	(2)	(3)	3% Inflation per y	/ear	(4)					
			PROGRAMMED EXPENDITURES & FUNDING SOURCES (FS) (000's)							
PROJ. NO.	PROJECT TITLE	PROJ. PRIO.	2004-2005 FS	2005-2006 FS	2006-2007 FS	2007-2008 FS	2008-2009 FS	2009-2010 FS		
1	Renovate Bennett Martin	В					10,787.8 GO			
	Public Library									
2	Resurface Gere Branch	В		110.0 GR						
-	Library Parking Lot			110.0 01	·					
	56th & Normal									
3	Replace Roof of South	В		22.0						
	Branch Library  27th & South Streets			33.2 GR						
	27 11 0 00011 0110010									
4	Replace Roof of Bennett	В		23.1 GR						
	Martin Public Library, Unit 1,									
	South Portion, 14th & N Sts.									
5	Replace Roof of Bethany	В		24.5 GR						
	Branch Library, 1810 No.									
	Cotner									
_										
6	Replace Cooling Tower at Bennett Martin Public Library	В			50.0 GR					
	Defined martin asia Listary									
*7	Replace Roof of Bennett						50.5 GR			
	Martin Public Library, Unit 1, West Portion, 14th & N Sts.									
	West Guon, 14th and Gs.									
	FUNDING SOURCE BREAKDOWN:									
	GO (General Obligation Bonds)		0.0	0.0	0.0	0.0	10,787.8	0.0		
	GR (General Revenue)		0.0	190.8	50.0	0.0	50.5	0.0		
	DEPARTMENT TOTAL:		0.0	190.8	50.0	0.0	10,838.3	0.0		
	DELAKTIVIENT TOTAL.		0.0	190.0	30.0	0.0	10,030.3	0.0		
					1	I				

TOTAL FOR   REYOND   REYOND												FORM B	
TOTAL FOR   BEYOND   BEYOND	(5)	(6)	(7)	(8)	(9)	(10)				(11)			(1)
TOTAL FOR   BEYOND   SERVIND   SERVIND   CAP COSTS   COMP   STATUS   CONFIDENCIATIONS   CONFIDENCIATIONS   CONFIDENCIATIONS   CONFIDENCIATIONS   CONFIDENCIATION   CONFIDENC		соѕт		TOTAL			COST	BREAKDOW	NS FOR SIX		ENDITURES	(000's)	
	TOTAL FOR SIX YEARS					1	PRELIM	FINAL			EQUIP /	OTHER	PRO
110.0 None None 110.0 GCP 1 6.4 103.6 Fees Tests Reimburse 2  33.2 None None 33.2 GCP 1 33.2 33.2 33.2 None None 23.1 GCP 1 23.1 4  24.5 None None So.0 GCP 1 24.5 5  50.0 None None So.0 GCP 1 50.0 50.0 6  50.5 None None So.5 GCP 1 50.5 7	ľ			(5)+(6)+(7)					TION				NO.
23.1 None None 23.1 GCP 1 23.1 4  24.5 None None 24.5 GCP 1 24.5 5  50.0 None None 50.0 GCP 1 50.5 None None 50.5 GCP 1 50.5 **  10,787.8 291.3 **							20.0				1941.6	Fees Tests	2
24.5 None None 24.5 GCP 1 24.5 5  50.0 None None 50.0 GCP 1 50.0  6  50.5 None None 50.5 GCP 1 50.5	33.2	None	None	33.2	GCP	1				33.2			3
50.0 None None 50.0 GCP 1 50.0 66  50.5 None None 50.5 GCP 1 50.5	23.1	None	None	23.1	GCP	1				23.1			4
50.5 None None 50.5 GCP 1 50.5 *:	24.5	None	None	24.5	GCP	1				24.5			5
10,787.8 291.3	50.0	None	None	50.0	GCP	1				50.0			6
291.3	50.5	None	None	50.5	GCP	1				50.5			*7
	291.3 ======												
Page N-1 (b													(b)

This page left blank intentionally.