### Project Summary and Justification

Department	Lincoln City Libraries
Division	Administration

#### **Project 1** Bennett Martin Public Library Renovation

The Bennett Martin Public Library, constructed in three phases (1962, 1968, 1978) is in need of renovation. Renovation will provide a modernized facility, which will be able to accommodate the requirements for expanded automated services and technology. The renovation will also include a complete replacement of the heating, ventilating, and air conditioning systems. It will also include replacement of a significant portion of the furniture and fixtures. In the 2002/2003 CIP, this project had a projected cost of \$8,149,500.00 in 2006/2007 dollars. Based on information provided by the Clark Enersen Partners as part of the Space Needs Survey that we are currently conducting, this has been revised to \$9,240,000.00 in 2002/2003 dollars. Using an inflation factor of 5% per year this equates to \$11,235,700 in 2006/2007 dollars.

#### **Project 2** Gere Branch Library Parking Lot Resurfacing

The Gere Branch Library parking lot and accompanying drives, approximately 46,000 square feet, were constructed in 1971. In 1986 they were overlaid utilizing 2" of Type III asphalt and petro-mat. In 1993 approximately 16,000 square feet of additional parking area was added as part of the Gere Branch expansion project. In the fall of 1996 potholes began appearing in the surface of the lot. The lot has been adequately maintained through repairs for a period of approximately 5 years. In addition to the resurfacing of the entire lot, structural repairs are required on a minimum of 10% of the lot surface area prior to resurfacing operations.

#### **Project 3** South Branch Library Roof Replacement

The current roof, a loosely laid, ballasted, EPDM membrane system, was installed in 1986 and was warranted for a period of ten years. During the summer of 1998 we began to experience problems with leakage. Multiple repairs were made extending the life of the roof by approximately 5 years. It is recommended that the roof be replaced in fiscal year 2003-2004; however, due to funding limitations request is being made for funding in FY 2005-2006.

#### Project 4 Bennett Martin Public Library Roof Replacement, South Portion Unit #1

This roof is a loosely laid, ballasted, EPDM membrane system. Installation was completed in the fall of 1987 and is covered by a 15 year water-tight warranty. This warranty expired in the fall of 2002. Based on current experiences it is requested that this roof be replaced in FY 2002-2003; however, due to funding limitations request is being made for funding in FY 2005-2006.

#### Project 5 Bethany Branch Library Roof Replacement

The existing roof is a fully adhered EPDM membrane system. It was installed in 1989 and carries a 15-year watertight warranty. Based on current experiences it is recommended that this roof be replaced when the warranty expires in 2004. However, due to funding limitations, the request for funding is being made in FY 2005-2006.

#### **Project 6** Bennett Martin Public Library Cooling Tower Replacement:

The cooling tower serving unit #3 (3<sup>rd</sup> & 4<sup>th</sup> floors) at Bennett Martin Public Library needs to be replaced due to deterioration of the tower body. The cooling tower was installed in 1978 as part of the Unit #3 addition. Problems with corrosion damage to the tower structure have plagued us since 1994. During this


time period we have replaced the air plenum and a section of the tower wall. We have also sealed numerous small leaks in the reservoir section of the tower. Currently the cooling tower is located within the confines of the building, which makes service difficult and necessitates that a portion of the north wall of the building be removed and replaced to allow for replacement of the cooling tower. The cost of replacing the tower includes funds to move the cooling tower to the roof. We have determined that the cooling tower needs to be replaced in FY 2002-2003 at a cost of \$54,300. However, due to general revenue limitations, the project had been placed in FY 2006-2007 at a cost of \$50,000, which includes no inflation factor.
*Not included in previous Capital Improvement Program

This page left blank intentionally.	

# *Lincoln CIP* 2003 - 2009

## Libraries





List of Projects Department: Lincoln City Libraries

Project Project Number Title

- 1 Bennett Martin Public Library Renovation
- 2 Gere Branch Library Parking Lot Resurfacing
- 3 South Branch Library Roof Replacement
- 4 Bennett Martin Public Library Roof Replacement, South Portion Unit #1
- 5 Bethany Branch Library Roof Replacement
- 6 Bennett Martin Public Library Cooling Tower Replacement

<sup>\*</sup> Indicates project is NOT shown on the map.

1)	(2)	(3)	5% Inflation per y	ear	(4)			
.,	\=/	(0)	0 /0 mma.com por )					
OJ.		PROJ.		PROGRAMMED E	XPENDITURES & F	UNDING SOURCES	(FS) (000's)	
IO.	PROJECT TITLE	PRIO.	2003-2004 FS	2004-2005 FS	2005-2006 FS	2006-2007 FS	2007-2008 FS	2008-2009 I
1	Renovate Bennett Martin Public Library	В				11,235.7 GO		
2	Resurface Gere Branch Library Parking Lot 56th & Normal	В		110.0 GR				
	Replace Roof of South Branch Library 27th & South Streets	В			33.2 GR			
	Replace Roof of Bennett Martin Public Library, Unit 1, South Portion, 14th & N Sts.	В			23.1 GR			
	Replace Roof of Bethany Branch Library, 1810 No. Cotner	В			24.5 GR			
	Replace Cooling Tower at Bennett Martin Public Library	В				50.0 GR		
	FUNDING SOURCE:							
	GO (General Obligation Bonds)		0.0	0.0	0.0	11,235.7	0.0	0.0
	GR (General Revenue)		0.0	110.0	80.8	50.0	0.0	0.0
	DEPARTMENT TOTAL:		0.0	110.0	80.8	11,285.7	0.0	0.0

												FORM B	
(5)	(6)		(7)	(8)	(9)	(10)				(11)			(1)
TOTAL FOR	COST BEYOND 2008-2009	PRIOR APPROPRIATION	ıs	TOTAL CAP COSTS (000's)	COMP PLAN	STATUS	COST I	BREAKDOW FINAL	INS FOR SIX	-YEAR EXPE	EQUIP /	(000's)	PRO.
(000's)	(000's)	(000's)	YEAR FS	(5)+(6)+(7)	CONFORM	PLANS	PLANS	PLANS	TION	CONST	FURNISH	(EXPLAIN)	NO.
11,235.7 110.0	0.0	0.0	96-97 GF	11,255.7	GCP GCP	1	20.0	414.7 6.4	0.0	8,171.5 103.6	2042.8	Fees Tests Reimburse	2
33.2	0.0	0.0		33.2	GCP	1				33.2			3
23.1	0.0	0.0		23.1	GCP	1				23.1			4
24.5	0.0	0.0		24.5	GCP	1				24.5			5
50.0	0.0	0.0		50.0	GCP	1				50.0			6
11,235.7 240.8 ========= 11,476.5													

This page left blank intentionally.
This page left blank intentionally.